

# Phase-sequence Phase-loss Relay K8AB-PH1-L

## Three-phase Phase-sequence Phase-loss Relay Using Voltage Detection Method Fixed phase Asymmetry monitoring

- Prevents reverse motor rotation due to incorrect wiring.
- Distinguishes between positive phases, reversed phases, and phase loss when power is turned ON.
- Voltage detection method enables application for any load current.
- One SPDT output relay, 6 A at 250 VAC (resistive load).
- Output status can be monitored using LED indicator.



### **Model Number Structure**

### **Model Number Legend**

**K8AB**-□□□-□

1 2 3 4

1. Basic Model

K8AB: Measuring and Monitoring Relays

2. Functions

PH: Phase-sequence Phase-loss Relay

3. Rated Input Voltage

1: 200 to 500 VAC

4. Type

Economy type

### **Ordering Information**

### **List of Models**

Phase-sequence Phase-loss Relay	Functions	Rated input voltage *	Model
	Phase sequence and phase loss monitoring	200 to 500 VAC	K8AB-PH1-L

<sup>\*</sup>The power supply is shared with the rated input voltage.

## K8AB-PH1-L

## **Ratings and Specifications**

## Ratings

Rated input voltage	Three-phase, three-wire mode, 200 to 500 VAC	
Input load	15 VA max.	
Reversed phase and phase loss operating time	0.1 s max.	
Reset method	Automatic reset	
Indicators	Power (PWR): Green, Relay output (RY): Yellow	
Output relays	One SPDT relay (NC operation)	
Output relay ratings	Rated load Resistive load $6 \text{ A at } 250 \text{ VAC } (\cos \phi = 1)$ $6 \text{ A at } 30 \text{ VDC } (L/R = 0 \text{ ms})$ Inductive load $1 \text{ A at } 250 \text{ VAC } (\cos \phi = 0.4)$ $1 \text{ A at } 30 \text{ VDC } (L/R = 7 \text{ ms})$ Maximum contact voltage: Maximum contact current: $6 \text{ A AC}$ Maximum switching capacity: Minimum load: Minimum load: Mechanical life:  Electrical life:  Make: 25,000 times, Break: 15,000 times	
Ambient operating temperature	-20 to 60°C (with no condensation or icing)	
Storage temperature	-40 to 70°C (with no condensation or icing)	
Ambient operating humidity	25% to 85% (with no condensation)	
Storage humidity	25% to 85% (with no condensation)	
Altitude	2,000 m max.	
Terminal screw tightening torque	0.54 N·m	
Terminal wiring method	Recommended wire Solid wire: 2.5 mm² Twisted wires: AWG16, AWG18 Note: 1. Ferrules with insulating sleeves must be used with twisted wires. 2. Two wires can be twisted together. Recommended ferrules AI 1,5-8BK (for AWG16) manufactured by Phoenix Contact AI 1-8RD (for AWG18) manufactured by Phoenix Contact AI 0,75-8GY (for AWG18) manufactured by Phoenix Contact	
Case color	Munsell 5Y8/1	
Case material	ABS resin (self-extinguishing resin) UL94-V0	
Weight	Approx. 110 g	
Mounting	Mounted to DIN Track or via M4 screws (tightening torque: 1.2 N⋅m)	
Dimensions	22.5 (W) × 90 (H) × 100 (D) mm	


### **Specifications**

Input voltage range	200 to 500 VAC	
Input frequency range	45 to 65 Hz	
Overload capacity	Continuous input: 115% of maximum input, 10 s max.: 125% of maximum input	
Fixed Phase Asymmetry Monitoring	Output relay releases when one phase-phase voltage drops below 80% of the other phase phase voltage.	
Temperature influence	Operating time Fluctuation based on measured value at standard temperature: -20°C to standard temperature: ±10% max. Standard temperature to 60°C: ±10% max. (Humidity: 25% to 80%)	
Humidity influence	Operating time Based on ambient room humidity 25% to 80%: ±10% max.	
Influence of power supply voltage	Operating time: ±10% max.  Note: The error in the operating value and operating time under standard conditions.	
Influence of power supply frequency	Operating time: ±10% max. (at 45 to 65 Hz)  Note: The error in the operating value and operating time under standard conditions.	
Influence of input frequency	At 45 to 65 Hz Operating time: ±10% max.  Note: The error in the operating value and operating time under standard conditions.	
Insulation resistance	20 MΩ min.  Between external terminals and case Between input terminals and output terminals	
Dielectric strength	2,000 VAC for one minute  Between external terminals and case  Between input terminals and output terminals	
Noise immunity	1,500 V power supply terminal common/normal mode Square-wave noise of ±1 μs/100 ns pulse width with 1-ns rise time	
Vibration resistance	Frequency 10 to 55 Hz, 0.35-mm single amplitude, acceleration 50 m/s <sup>2</sup> 10 sweeps of 5 min each in X, Y, and Z directions	
Shock resistance	100 m/s², 3 times each in 6 directions along three axes (up/down, left/right, forward/backward)	
Degree of protection	Terminal section: Finger protection	

### **Connections**


### **Wiring Diagram**

### **Phase Sequence and Phase Loss Operation Diagram**




Note: 1. The K8AB-PH1-L output relay is normally operative.

- 2. L1 and L3 function both as the power supply terminals and as input terminals. If the voltage drops below the minimum input voltage (60%), then the Relay will not operate due to an undervoltage.
- There is a risk of internal circuit breakage by high frequency waves. Don't use the product at the load side of inverter.



### **Nomenclature**

### **Front**



### **Indicators**

Item	Meaning
Power indicator (PWR: Green)	Lit when power is being supplied *3.
Relay status indicator (RY: Yellow)	Lit when relay is operating (normally lit).

- \*1. The input across L1 and L3 is used for the internal power supply. Therefore, the power indicator will not be lit if there is no input across L1 and L3.
- \*2. Use either a solid wire of 2.5 mm<sup>2</sup> maximum or a ferrule with insulating sleeve for the terminal connection.

The length of the exposed current-carrying part inserted into the terminal must be 8 mm or less to maintain dielectric strength after connection.



Recommended ferrules

**Phoenix Contact** 


- Al 1,5-8BK (for AWG16)
- Al 1-8RD (for AWG18)
- Al 0,75-8GY (for AWG18)
- **\*3.** Tightening torque

Recommended: 0.54 N·m Maximum: 0.59 N·m

## **Operation and Setting Methods Connections**

- 1. Input
  - Connect using L1, L2, and L3.
  - Make sure the phase sequence is wired correctly. The Unit will not operate normally if the phase sequence is incorrect.
- 2. Outputs


Terminals 11, 12, and 14 are output terminals for SPDT.




Dimensions (Unit: mm)

# Phase-sequence, Phase-loss Relays K8AB-PH1-L







### **Safety Precautions**

### **Precautions for Safe Use**

Make sure to follow the instructions below to ensure safety.

- 1. Do not use or keep this product in the following environments.
  - Outdoors, or places subject to direct sunlight or wearing weather.
  - Places where dust, iron powder, or corrosive gases (in particular, sulfuric or ammonia gas) exist.
  - Places subject to static electricity or inductive noise.
  - Places where water or oil come in contact with the product.
- 2. Make sure to install this product in the correct direction.
- There is a remote risk of electric shock. Do not touch terminals while electricity is being supplied.
- Make sure to thoroughly understand all instructions in the Instructions Manual before handling this product.
- Make sure to confirm terminal makings and polarity for correct wiring.
- 6. Tighten terminal screws firmly using the following torque.

  Recommended tightening torque: 0.54 N⋅m

  Maximum tightening torque: 0.59 N⋅m max.
- Operating ambient temperature and humidity for this product must be within the indicated rating when using this product.
- There is a remote risk of explosion. Do not use this product where flammable or explosive gas exists.
- 9. Make sure that no weight rests on the product after installation.
- 10.To enable an operator to turn off this product easily, install switches or circuit breakers that conform to relevant requirements of IEC60947-1 and IEC60947-3, and label them appropriately.

## Precautions for Correct Use For Proper Use

- 1. Do not use the product in the following locations.
  - Places subject to radiant heat from heat generating devices.
  - Places subject to vibrations or physical shocks.
- Make sure to use setting values appropriate for the controlled object. Failure to do so can cause unintended operation, and may result in accident or corruption of the product.
- 3. Do not use thinner or similar solvent for cleaning. Use commercial alcohol.
- When discarding, properly dispose of the product as industrial waste.
- Only use this product within a board whose structure allows no possibility for fire to escape.
- 6. This is a class A product. In residential areas it may cause radio interference, in which case the user may be required to take adequate measures to reduce interference.

### **About Installation**

- 1. When wiring, use only recommended crimp terminals.
- Do not block areas around the product for proper dissipation of heat. (If you do not secure space for heat dissipation, life cycle of the product will be compromised.)
- 3. To avoid electrical shocks, make sure that power is not supplied to the product while wiring.
- 4. To avoid electrical shocks, make sure that power is not supplied to the product when performing DIP switch settings.

### **Noise Countermeasures**

- Do not install the product near devices generating strong high frequency waves or surges.
- 2. When using a noise filter, check the voltage and current and install it as close to the product as possible.
- In order to prevent inductive noise, wire the lines connected to the product separately from power lines carrying high voltages or currents. Do not wire in parallel with or on the same cable as power lines.
  - Other measures for reducing noise include running lines along separate ducts and using shield lines.

# To avoid faulty operations, malfunctions, or failure, observe the following operating instructions.

- 1. When turning on the power, make sure to realize rated voltage within 1 second from the time of first supply of electricity.
- Make sure to use power supply for operations, inputs, and transformer with the appropriate capacity and rated burden.
- 3. Maintenance and handling of this product may only be performed by qualified personnel.
- 4. Distortion ratio of input wave forms must be 30% or less. Use of this product with circuits that have large distortion in wave forms may result in unwanted operations.
- **5.** Properly connect phase sequence.
- 6. The type K8AB-PH1-L can only detect phase interruption when the interruption occurs on the side where power supply exists from the point of connection, and interruption on the loading side cannot be detected.
- 7. This product cannot be used for thyristor controls or inverters.
- 8. There is a risk of internal circuit breakage by high frequency waves. Don't use the product at the load side of inverter.

### **Questions and Answers**



### **Checking Operation**




Phase Sequence

Switch the wiring, as shown by the dotted lines in the connection diagram, to reverse the phase sequence and check that the K8AB operates.

Phase Loss

Create a phase loss for any input phase and check that the K8AB operates.

### **Connection Diagram**





### Can phase loss be detected on the load side?



In principle, phase loss cannot be detected on the load side because the K8AB-PH1-L measures three-phase voltage to determine phase loss.

## Q

### **Motor Load Phase Loss during Operation**





Motor load phase loss can be detected during operation only when the motor has heavy load.

Please use it with understanding the following characteristics.

Normally, three-phase motors will continue to rotate even if one phase is open. The three-phase voltage will be induced at the motor terminals. The diagram shows voltage induction at the motor terminals when phase R has been lost with a load applied to a three-phase motor. The horizontal axis shows the motor load as a percentage of the rated load, and the vertical axis shows voltage as a percentage of the rated voltage. The lines in the graph show the voltage induced at the motor terminals for each load when phase loss occurs during operation. As the graph shows, voltage is induced at the motor terminals even if there is phase loss for a motor load, so K8AB-PH1-L can detect phase loss for motor loads during operation with the condition of following graph. K8AB-PH1-L can detect phase loss when startup without condition.

### **Characteristic Curve Diagram**





Note: 1. For phase loss of phase R. Vst, Vtr, and Vrs indicate the motor terminal voltage at phase loss.

- This graph shows that K8AB-PH1-L can detect phase loss during operation when the motor load is more than 50%.
- This is a general example and it doesn't guarantee the characteristics. Use K8AB-PH1-L in view of the motor characteristics.

MEMO

### Warranty and Application Considerations

### Read and Understand this Catalog

Please read and understand this catalog before purchasing the products. Please consult your OMRON representative if you have any questions or comments.

### Warranty and Limitations of Liability

### **WARRANTY**

OMRON's exclusive warranty is that the products are free from defects in materials and workmanship for a period of one year (or other period if specified) from date of sale by OMRON.

OMRON MAKES NO WARRANTY OR REPRESENTATION, EXPRESS OR IMPLIED, REGARDING NON-INFRINGEMENT. MERCHANTABILITY, OR FITNESS FOR PARTICULAR PURPOSE OF THE PRODUCTS. ANY BUYER OR USER ACKNOWLEDGES THAT THE BUYER OR USER ALONE HAS DETERMINED THAT THE PRODUCTS WILL SUITABLY MEET THE REQUIREMENTS OF THEIR INTENDED USE. OMRON DISCLAIMS ALL OTHER WARRANTIES, EXPRESS OR IMPLIED.

#### LIMITATIONS OF LIABILITY

OMRON SHALL NOT BE RESPONSIBLE FOR SPECIAL, INDIRECT, OR CONSEQUENTIAL DAMAGES, LOSS OF PROFITS, OR COMMERCIAL LOSS IN ANY WAY CONNECTED WITH THE PRODUCTS, WHETHER SUCH CLAIM IS BASED ON CONTRACT, WARRANTY, NEGLIGENCE, OR STRICT LIABILITY.

In no event shall the responsibility of OMRON for any act exceed the individual price of the product on which liability is asserted. IN NO EVENT SHALL OMRON BE RESPONSIBLE FOR WARRANTY, REPAIR, OR OTHER CLAIMS REGARDING THE PRODUCTS UNLESS OMRON'S ANALYSIS CONFIRMS THAT THE PRODUCTS WERE PROPERLY HANDLED, STORED, INSTALLED, AND MAINTAINED AND NOT SUBJECT TO CONTAMINATION, ABUSE, MISUSE, OR INAPPROPRIATE MODIFICATION OR REPAIR.

### **Application Considerations**

### SUITABILITY FOR USE

OMRON shall not be responsible for conformity with any standards, codes, or regulations that apply to the combination of products in the customer's application or use of the products.

Take all necessary steps to determine the suitability of the product for the systems, machines, and equipment with which it will be used. Know and observe all prohibitions of use applicable to this product.

NEVER USE THE PRODUCTS FOR AN APPLICATION INVOLVING SERIOUS RISK TO LIFE OR PROPERTY WITHOUT ENSURING THAT THE SYSTEM AS A WHOLE HAS BEEN DESIGNED TO ADDRESS THE RISKS, AND THAT THE OMRON PRODUCTS ARE PROPERLY RATED AND INSTALLED FOR THE INTENDED USE WITHIN THE OVERALL EQUIPMENT OR SYSTEM.

### **Disclaimers**

### **PERFORMANCE DATA**

Performance data given in this catalog is provided as a guide for the user in determining suitability and does not constitute a warranty. It may represent the result of OMRON's test conditions, and the users must correlate it to actual application requirements. Actual performance is subject to the OMRON Warranty and Limitations of Liability.

### **CHANGE IN SPECIFICATIONS**

Product specifications and accessories may be changed at any time based on improvements and other reasons. Consult with your OMRON representative at any time to confirm actual specifications of purchased product.

### **DIMENSIONS AND WEIGHTS**

Dimensions and weights are nominal and are not to be used for manufacturing purposes, even when tolerances are shown.

### ALL DIMENSIONS SHOWN ARE IN MILLIMETERS.

To convert millimeters into inches, multiply by 0.03937. To convert grams into ounces, multiply by 0.03527.

**OMRON Corporation Industrial Automation Company** 

Tokyo, JAPAN

Contact: www.ia.omron.com

Regional Headquarters **OMRON EUROPE B.V.** 

Wegalaan 67-69-2132 JD Hoofddorp The Netherlands

Tel: (31)2356-81-300/Fax: (31)2356-81-388

OMRON ASIA PACIFIC PTE. LTD.

No. 438A Alexandra Road # 05-05/08 (Lobby 2). Alexandra Technopark, Tel: (65) 6835-3011/Fax: (65) 6835-2711

**OMRON ELECTRONICS LLC** 

One Commerce Drive Schaumburg, IL 60173-5302 U.S.A. Tel: (1) 847-843-7900/Fax: (1) 847-843-7787

OMRON (CHINA) CO., LTD. Room 2211, Bank of China Tower, 200 Yin Cheng Zhong Road, PuDong New Area, Shanghai, 200120, China Tel: (86) 21-5037-2222/Fax: (86) 21-5037-2200 Authorized Distributor:

© OMRON Corporation 2010 All Rights Reserved. In the interest of product improvement, specifications are subject to change without notice.

Printed in Japan Cat. No. N161-E1-03